

CONTINUED AIRWORTHINESS MANAGEMENT OTAR 39 SUBPART F AUTHORISATION

Authorisation Reference:	BDA/SF/061
SIA "ASB", "FLIGHT SUPPORT" BRANCH	
Dorogobuzhskaya str., 14 building 5 Moscow 121354 Russian Federation	

Pursuant to the provisions of Article 26 of the Air Navigation (Overseas Territories) Order 2013, as amended, the above named organisation is hereby authorised to the requirements of OTAR 39 Subpart F.

CONDITIONS OF AUTHORISATION


This authorization is subject to continued compliance with SIA "ASB", "FLIGHT SUPPORT" BRANCH Maintenance Control Manual Issue 3 Rev 0. Any amendments to the Maintenance Control Manual requires Bermuda Civil Aviation Authority acceptance.

The scope of work authorised by this document is defined in the Maintenance Control Manual Issue 3 Rev 0 for the performance of continued airworthiness management on Bermuda registered aircraft.

RATING:	SCOPE OF WORK:
<ul style="list-style-type: none"> Airbus A320 Bombardier CL 600-2B19 Bombardier CL 601-3A Boeing 737-500 Boeing B757-200 Boeing 777-200 Embraer EMB-135 Legacy Embraer EMB-145LR Hawker 850XP Hawker 750 Hawker BAE 125 1000A Hawker Beechjet 400/400A 	<p>As defined in the Maintenance Control Manual Issue 3 Rev 0 dated 01.08.2018 for the performance of continued airworthiness management on Bermuda registered aircraft.</p>

DATE OF VALIDITY:	DATE OF EXPIRY:
28 August 2018	31 August 2019


 Denis Glasford, Senior Airworthiness Inspector
 Bermuda Civil Aviation Authority



28 August 2018
 Date of Reissue