



**AIRSUP.LV**



**AIRLINE SUPPORT BALTIC**



---

## **Throughout all phases of the process**

**We've done this interior literally from scratch. The aircraft used to be located in a place with improper conditions (hot and humid climate), which definitely didn't affect it well (see the "before" pictures). It was a laborious project that we've enjoyed a lot. Such satisfaction to see it on the way to some final touches.**

The image shows the interior of a vehicle, specifically the front passenger area. Two leather seats are visible, upholstered in a light tan or beige color. The seats show signs of wear, including scuffing and discoloration, particularly on the seat cushions and the lower backrest areas. The seats are positioned on a grey carpet. To the right of the seats, there is a wooden dashboard or console with two circular cup holders. A white rectangular box is overlaid on the right side of the image, containing the word "BEFORE" in bold black capital letters. The overall lighting is bright, likely from a window on the right side of the frame.

**BEFORE**

**BEFORE**



# Customizing with modern design, luxury materials & craftsmanship





## Full list of work performed

- custom carpet manufacturing and installation
- replating of metal parts with customized finishes
- LED upgrade
- re-veneering
- veneer color adjustments
- re-webbing of seatbelts
- change of seats and divan dresscover
- reupholstering of dado panels/windowliners/headliners
- countertop replacement staron / corian in galley, FWD lavatory, AFT lavatory
- production of new curtains and protection covers
- interior placards and markings
- airstairs refurbishment NTF and paint



**AIRLINE SUPPORT BALTIC**

# Contact details



## Headquarters

Skultes street 50/15,  
Skulte, Latvia  
LV-2108



## Phone & Mobile

+371 26904918



## Email Address

[sales@airsup.lv](mailto:sales@airsup.lv)



## Website

[www.airsup.lv](http://www.airsup.lv)